Appendix 3

Appendix 3 Cost Summary by Access Type					
	Priority 1	Priority 2	Priority 3	Priority 4	
	DDA	Improvement	Best Practice	Operational	Total
Section 1 : External Circulation	£68,200.00	£31,010.00	£4,755.00	£4,650.00	£108,615.00
Section 2 : Building Entrance	£106,435.00	£33,790.00	£17,120.00	£14,715.00	£172,060.00
Section 3 : Reception	£6,700.00	£1,800.00	£300.00	£0.00	£8,800.00
Section 4 : Corridors / Circulation	£400.00	£135.00	£8,190.00	£475.00	£9,200.00
Section 5 : Internal Stairs	£30,825.00	£108,730.00	£20,725.00	£9,475.00	£169,755.00
Section 6: Internal Ramps	£200.00	£4,400.00	£4,625.00	£3,750.00	£12,975.00
Section 7 : Internal Doors	£15,750.00	£67,495.00	£2,530.00	£20,460.00	£106,235.00
Section 8: Wayfinding / Means of Escape	£2,900.00	£40,245.00	£18,650.00	£5,775.00	£67,570.00
Section 9 : Toilet Facilities	£35,440.00	£38,160.00	£12,805.00	£6,665.00	£93,070.00
Section 10 : Accessible Toilets	£56,855.00	£12,530.00	£5,825.00	£1,800.00	£77,010.00
Section 11 : Employee Facilities	£1,500.00	£2,400.00	£15,300.00	£2,940.00	£22,140.00
Section 12 : Communal Facilities	£15,500.00	£5,815.00	£2,200.00	£400.00	£23,915.00
Total	£340,705.00	£346,510.00	£113,025.00	£71,105.00	£871,345.00